



Clamp 01 : Small cables

COMPONENTS




STRIPPING DIMENSIONS




1

Slide the back nut onto the cable.
Strip the cable.
Cut 2 slots in the jacket if necessary.




4

Solder the centre contact onto the inner conductor.
Slide the back nut over the cable assembly.




2

Slide the clamp braid sleeve between the cable dielectric and the braid.




5

Mount the gasket into the body.



3

Cut the braid flush with the clamp braid sleeve.
Slide the spacer onto the cable.
Slide the centre contact on until it bottoms against the cable dielectric.



6

Screw sub-assembly into the connector body with the adapted wrench.
Recommended coupling torque (see connector TDS).

