

From: Alastair French [<mailto:Alastair.French@uk.ebmpapst.com>]
Sent: 29 January 2015 14:25
To: Burns, Michael
Cc: Sandra Jarvis
Subject: 8452/2GHHP (800 4306)

Hello Michael

We have been informed of a product specification change affecting the 8450 series.

Please note this only affects the sleeve bearing models i.e. those having a 'G' in the type designation with the 8452/2GHHP being the only model that you take. From a field experience there is a confirmed risk that under worst case conditions and maximum temperature that the fan could stop in the mounting position "shaft vertical, rotor down", therefore this position can no longer be specified. The alternative positions i.e. "shaft horizontal" and "shaft vertical, rotor up" are however still okay.

Of course please feel free to contact me if you require any additional information.

Kind regards

Alastair French

Key Account Co-ordinator

ebm-papst UK Ltd

Chelmsford Business Park,

CM2 5EZ Chelmsford,

UK

Tel: +44 (0) 1245 468555

Dir: +44 (0) 1245 456526

Alastair.French@uk.ebmpapst.com

www.ebmpapst.co.uk

