

PX-2 SERIES

FIBER
SENSORSLASER
SENSORSPHOTOELECTRIC
SENSORSMICRO
PHOTOELECTRIC
SENSORSAREA
SENSORSLIGHT
CURTAINSPRESSURE /
FLOW
SENSORSINDUCTIVE
PROXIMITY
SENSORSPARTICULAR
USE SENSORSSENSOR
OPTIONSSIMPLE
WIRE-SAVING
UNITSWIRE-SAVING
SYSTEMSMEASUREMENT
SENSORSSTATIC CONTROL
DEVICES

ENDOSCOPE

LASER
MARKERSPLC /
TERMINALSHUMAN MACHINE
INTERFACESENERGY CONSUMPTION
VISUALIZATION
COMPONENTS

FA COMPONENTS

MACHINE VISION
SYSTEMSUV CURING
SYSTEMSSelection
Guide

Wafer Detection

Liquid Leak
DetectionLiquid Level
Detection

Water Detection

Color Mark
DetectionHot Melt Glue
Detection

Ultrasonic

Small /
Slim Object
DetectionObstacle
Detection

Other Products

Related Information

■ General terms and conditions..... F-17

■ Glossary of terms..... P.1359~

■ Sensor selection guide..... P.831~


■ General precautions..... P.1405

Conforming to
EMC Directive
panasonic-electric-works.net/sunx

Compact size sensor realizes wide sensing area & long sensing range

Ideal sensing area with very little null zone


The advanced optical system of the **PX-2** series reduces the null zones in front of an automatic guided vehicle (AGV). The null zones at the sides are further minimized if auxiliary sensors which can be easily mounted with connectors are used.
(For **PX-24**, **PX-24ES**, **PX-23ES** and **PX-26**)



Sensing areas selectable as per route condition


Sensing areas can be selected with switches to suit the route conditions of an AGV.

Further, in case of **PX-24ES** and **PX-23ES**, the sensing areas can also be selected with external signals.



Compact size for space-saving

Its size is half of a conventional model, and the attached cable orientation is freely adjustable. Hence, it can also fit in a small AGV. Moreover, sensitivity adjustment can be done on the front face.



Long sensing range 5 m 16.404 ft type

PX-26 has a long sensing range of 5 m 16.404 ft. Even on a high-speed AGV, it can detect an object quite early so that slowing down and stopping are smooth.

Automatic interference prevention function

One **PX-2** sensor can simultaneously receive beams from 25 Nos. of other **PX-2** sensors without resulting in any interference. Even if AGVs are facing each other, the **PX-2** sensor on one AGV reliably detects the other AGVs. Hence, it can be safely used even at a place where several AGVs are moving.

Sleep function

The sensor can be put into the sleep (stand-by) condition when it is not used and can be restored to operating condition by an external signal. Consequently battery is conserved as the power consumption is reduced to 1/5.


External sensitivity adjustment

The sensitivity of the sensor can be adjusted, within the range set by the manual adjuster, by an external input.
(For **PX-24**, **PX-24ES**, **PX-23ES** and **PX-26**)


PX-2

ORDER GUIDE**Main Sensor**

Type	Appearance	Sensing range	Model No.
Standard type		3 m 9.843 ft	PX-22
		1 m 3.281 ft	PX-21
Auxiliary sensor connectable type		3 m 9.843 ft	PX-24
			PX-24ES
		1 m 3.281 ft	PX-23ES
		5 m 16.404 ft	PX-26
Auxiliary sensor		700 mm 27.559 in	PX-SB1

Accessories• **MS-PX-2** (Main sensor mounting bracket)


Two bracket set
 Four M4 (length 8 mm
 0.315 in) screws with
 washers are attached.

• **MS-NX5-1** (Auxiliary sensor mounting bracket)


Two M4 (length 25 mm
 0.984 in) screws with
 washers and two M4 nuts
 are attached.

OPTIONS

Designation	Model No.	Description
Auxiliary sensor mounting bracket	MS-NX5-2	Foot biangled mounting bracket (Sensor protection bracket)
	MS-NX5-3	Back angled mounting bracket

Auxiliary sensor mounting bracket• **MS-NX5-2**

Two M4 (length 25 mm
 0.984 in) screws with
 washers and two M4 nuts
 are attached.

• **MS-NX5-3**

Two M4 (length 25 mm
 0.984 in) screws with
 washers and two M4 nuts
 are attached.

FIBER
SENSORSLASER
SENSORSPHOTO-
ELECTRIC
SENSORSMICRO
PHOTO-
ELECTRIC
SENSORSAREA
SENSORSLIGHT
CURTAINSPRESSURE /
FLOW
SENSORSINDUCTIVE
PROXIMITY
SENSORSPARTICULAR
USE
SENSORSSENSOR
OPTIONSSIMPLE
WIRE-
SAVING
UNITSWIRE-
SAVING
SYSTEMSMEASURE-
MENT
SENSORSSTATIC
CONTROL
DEVICES

ENDOSCOPE

LASER
MARKERSPLC /
TERMINALSHUMAN
MACHINE
INTERFACESENERGY
CONSUMPTION
VISUALIZATION
COMPONENTSFA
COMPONENTSMACHINE
VISION
SYSTEMSUV
CURING
SYSTEMSSelection
GuideWafer
DetectionLiquid Leak
DetectionLiquid Level
DetectionWater
DetectionColor Mark
DetectionHot Melt Glue
Detection

Ultrasonic

Small / Slim
Object DetectionObstacle
DetectionOther
Products**PX-2**

SPECIFICATIONS

Main sensors

Type		Standard model		Auxiliary sensor connectable model			
			Short sensing range		With external control function	Short sensing range	Long sensing range
Item	Model No.	PX-22	PX-21	PX-24	PX-24ES	PX-23ES	PX-26
Sensing range (OUT 1 and OUT 2 areas) (Note 2)		3 m 9.843 ft	1 m 3.281 ft	3 m 9.843 ft		1 m 3.281 ft	5 m 16.404 ft
Hysteresis (Note 2)		15 % or less of operation distance					
Supply voltage		10 to 31 V DC including ripple					
Power consumption (Note 3)		Under operation: 1.5 W or less, Under sleep condition: 0.3 W or less (without auxiliary sensor)					
OUT1 (OR circuit among the effective center, left, right, adjacent left / right OUT 1 areas and the effective auxiliary left / right areas)		NPN open-collector transistor • Maximum sink current: 100 mA • Applied voltage: 40 V DC or less (between OUT 1 / OUT 2 and 0 V) • Residual voltage: 1.5 V or less (at 100 mA sink current) 0.4 V or less (at 16 mA sink current)					
OUT2 (OR circuit among the effective center, left and right OUT 2 areas)							
Utilization category		DC-12 or DC-13					
Output operation		Selectable either Light-ON or Dark-ON with a switch (Output operation of OUT 1 and OUT 2 is the same.)					
Short-circuit protection		Incorporated					
Extraneous light monitor output		_____		NPN open-collector transistor • Maximum sink current: 100 mA • Applied voltage: 40 V DC or less (between extraneous light monitor output and 0 V) • Residual voltage: 1.5 V or less (at 100 mA sink current) 0.4 V or less (at 16 mA sink current)			
Output operation		_____		ON when modulated beam other than its own (including auxiliary sensor's) light is received			
Short-circuit protection		_____		_____			
Response time		80 ms or less					
Operation indicators	OUT 1 area	Red LED (lights up when the beam is received in the effective OUT 1 areas)					
	OUT 2 area	Yellow LED (lights up when the beam is received in the effective OUT 2 areas)					
Sensitivity adjuster		Continuously variable adjusters (OUT 1, adjacent right OUT 1, adjacent left OUT 1 and OUT 2 areas are adjusted independently.)					
External sensitivity adjustment function		_____		Sensitivity adjustment is possible with an analog input.			
Sensing area		Four sensing areas are selectable with dip switches.			Four sensing areas are selectable with dip switches, and eight sensing areas are selectable with external inputs.		Fixed
Sleep function		Operating / sleep selectable with external input					
Automatic interference prevention function		Optical interference from up to 25 units is prevented.					
Environmental resistance	Pollution degree	3 (Industrial environment)					
	Protection	IP65 (IEC)					
	Ambient temperature	-10 to +55 °C +14 to +131 °F (No dew condensation or icing allowed), Storage: -20 to +70 °C -4 to +158 °F					
	Ambient humidity	35 to 85 % RH, Storage: 35 to 85 % RH					
	Ambient illuminance	Incandescent light: 3,000 lx at the light-receiving face					
	EMC	EN 60947-5-2					
	Voltage withstandability	1,000 V AC for one min. between all supply terminals connected together and enclosure					
	Insulation resistance	20 MΩ, or more, with 500 V DC megger between all supply terminals connected together and enclosure					
	Vibration resistance	10 to 500 Hz frequency, 3 mm 0.118 in amplitude (20 G max.) in X, Y and Z directions for two hours each					
Shock resistance	500 m/s ² acceleration (50 G approx.) in X, Y and Z directions for three times each						
Emitting element		Infrared LED (Peak emission wavelength: 950 nm 0.037 mil, modulated)					
Material		Enclosure: ABS, Lens: Acrylic, Cover: Polycarbonate					
Cable		0.3 mm ² 5-core cabtyre cable, 0.5 m 1.640 ft long (for input and output)		For input and output: 0.18 mm ² 9-core (PX-24ES and PX-23ES: 12-core) cabtyre cable, 0.5 m 1.640 ft long For auxiliary sensor connection: 0.18 mm ² 10-core connector attached cabtyre cable, 0.5 m 1.640 ft long			
Cable extension		Extension up to total 100 m 328.084 ft (10 m 32.808 ft for auxiliary sensor connection) is possible with 0.3 mm ² , or more, cable.					
Weight		Net weight: 210 g approx. Gross weight: 390 g approx.			Net weight: 220 g approx. Gross weight: 400 g approx.		Net weight: 210 g approx. Gross weight: 390 g approx.
Accessories		MS-PX-2 (Main sensor mounting bracket): 1 set, Adjusting screwdriver: 1 pc., Matrix chart for sensing areas and external inputs: 1 sheet (PX-24ES and PX-23ES only)					

Notes: 1) Where measurement conditions have not been specified precisely, the conditions used were an ambient temperature of +23 °C **+73.4 °F**.

2) The sensing range is specified for white non-glossy paper (300 × 300 mm **11.811 × 11.811 in**) as the object.

3) Obtain the current consumption by the following calculation.

Current consumption = Power consumption ÷ Supply voltage


(e.g.) When the supply voltage is 12 V, the current consumption (operating condition) is: 1.5 W ÷ 12 V = 0.125 A = 125 mA

SPECIFICATIONS**Auxiliary sensor (Note 2)**


Item	Model No.	PX-SB1
Applicable main sensor		PX-24, PX-24ES, PX-23ES or PX-26
Connectable units		Up to two PX-SB1 's can be connected to one main sensor.
Sensing range (Note 3)		700 mm 27.559 in
Supply voltage		Supplied from the main sensor
Current consumption		Current consumption of the main sensor increases by 30 mA approx. per auxiliary sensor.
Output		OR circuit with the main sensor's OUT 1
Operation indicator		Red LED (lights up when the beam is received)
Sensitivity adjuster		Continuously variable adjuster
Emitting element		Infrared LED (modulated)
Material		Polycarbonate
Cable		0.3 mm ² 5-core cabtyre cable, 2 m 6.562 ft long
Cable extension		Extension up to total 10 m 32.808 ft is possible with 0.3 mm ² , or more, cable.
Weight		Net weight: 130 g approx., Gross weight: 240 g approx
Accessories		MS-NX5-1 (Auxiliary sensor mounting bracket): 1 set, Adjusting screwdriver: 1 pc.

Specifications other than the above are identical with the main sensor.

- Notes: 1) Where measurement conditions have not been specified precisely, the conditions used were an ambient temperature of +20 °C **+68 °F**.
 2) The auxiliary sensor cannot be used as a stand-alone unit.
 3) The sensing range is specified for white non-glossy paper (300 × 300 mm **11.811 × 11.811 in**) as the object.


I/O CIRCUIT AND WIRING DIAGRAMS**PX-24ES PX-23ES****I/O circuit diagram**

Symbols ... D: Reverse supply polarity protection diode
 ZD1, ZD2, ZD3: Surge absorption zener diode
 Tr1, Tr2, Tr3 : NPN output transistor

Wiring diagram

* 1

Non-voltage contact or NPN open-collector transistor



- Area selection input
 Low (0 to 1 V): Depends on the logic combination
 High (4.5 to 31 V, or open): Depends on the logic combination
- Auxiliary area ineffective input
 Low (0 to 1 V): Area ineffective
 High (4.5 to 31 V, or open): Area effective
- Sleep input
 Low (0 to 1 V): Sleep condition
 High [(supply voltage – 1 V) to 31 V, or open]: Operating condition

FIBER SENSORS

LASER SENSORS

PHOTO-ELECTRIC SENSORS

MICRO PHOTO-ELECTRIC SENSORS

AREA SENSORS

LIGHT CURTAINS

PRESSURE / FLOW SENSORS

INDUCTIVE PROXIMITY SENSORS

PARTICULAR USE SENSORS

SENSOR OPTIONS

SIMPLE WIRE-SAVING UNITS

WIRE-SAVING SYSTEMS

MEASURE-MENT SENSORS

STATIC CONTROL DEVICES

ENDOSCOPE

LASER MARKERS

PLC / TERMINALS

HUMAN MACHINE INTERFACES

ENERGY CONSUMPTION VISUALIZATION COMPONENTS

FA COMPONENTS

MACHINE VISION SYSTEMS

UV CURING SYSTEMS

Selection Guide

Wafer Detection

Liquid Leak Detection

Liquid Level Detection

Water Detection

Color Mark Detection

Hot Melt Glue Detection

Ultrasonic

Small / Sim Object Detection

Obstacle Detection


Other Products

PX-2

I/O CIRCUIT AND WIRING DIAGRAMS


PX-22 PX-21

I/O circuit diagram




Symbols ... D: Reverse supply polarity protection diode
 ZD1, ZD2: Surge absorption zener diode
 Tr1, Tr2 : NPN output transistor

Wiring diagram



* 1


Non-voltage contact or NPN open-collector transistor



- Sleep input
 Low (0 to 1 V): Sleep condition
 High [(supply voltage – 1 V) to 31 V, or open]: Operating condition


PX-24 PX-26

I/O circuit diagram




Symbols ... D: Reverse supply polarity protection diode
 ZD1, ZD2, ZD3: Surge absorption zener diode
 Tr1, Tr2, Tr3 : NPN output transistor

Wiring diagram




* 1

Non-voltage contact or NPN open-collector transistor




- Auxiliary area ineffective input
 Low (0 to 1 V): Area ineffective
 High (4.5 to 31 V, or open): Area effective
- Sleep input
 Low (0 to 1 V): Sleep condition
 High [(supply voltage – 1 V) to 31 V, or open]: Operating condition

SENSING CHARACTERISTICS (TYPICAL)**How to read sensing characteristics****Sensing field**


Note: The sensitivity has been adjusted so that the maximum sensing range for white non-glossy paper (300 × 300 mm 11.811 × 11.811 in) is 3 m 9.843 ft (1 m 3.281 ft for PX-21 and PX-23ES, 5 m 16.404 ft for PX-26) with the L., C. and R. areas effective.

Sensing area

L.: Left area
C.: Center area
R.: Right area
L': Adjacent left OUT 1 area
R': Adjacent right OUT 1 area

**Sensing object**










Type of non-glossy paper
White non-glossy paper (lightness: 9)
Gray non-glossy paper (lightness: 5)
Black non-glossy paper (lightness: 2)

Correlation between external sensitivity adjustment input voltage and sensing range

It shows the variation in the sensing range when the external input voltage is changed from 0 to +5 V with the sensitivity adjuster set at the maximum sensing range.

Correlation between sensitivity adjuster and sensing range

Please note that due to the adjuster's characteristics it may be difficult to adjust the sensitivity at a close distance or near to rated sensing distances. (Refer to "Correlation between sensitivity adjuster and sensing range" below.)

All models**Correlation between setting distance and excess gain****PX-22 PX-24 PX-24ES****Sensing fields****All areas effective (Horizontal)****C. area effective (Horizontal)****All areas effective (Vertical)****Correlation between external sensitivity adjustment input voltage and sensing range (Excluding PX-22)****Correlation between sensitivity adjuster and sensing range****OUT1(OUT2) area****Adjacent right (left) OUT1 area**

FIBER SENSORS

LASER SENSORS

PHOTO-ELECTRIC SENSORS

MICRO PHOTO-ELECTRIC SENSORS

AREA SENSORS

LIGHT CURTAINS

PRESSURE / FLOW SENSORS

INDUCTIVE PROXIMITY SENSORS

PARTICULAR USE SENSORS

SENSOR OPTIONS

SIMPLE WIRE-SAVING UNITS

WIRE-SAVING SYSTEMS

MEASURE-MENT SENSORS

STATIC CONTROL DEVICES

ENDOSCOPE

LASER MARKERS

PLC / TERMINALS

HUMAN MACHINE INTERFACES

ENERGY CONSUMPTION VISUALIZATION COMPONENTS

FA COMPONENTS

MACHINE VISION SYSTEMS

UV CURING SYSTEMS

Selection Guide

Wafer Detection

Liquid Leak Detection

Liquid Level Detection

Water Detection

Color Mark Detection

Hot Melt Glue Detection

Ultrasonic

Small / Sim Object Detection


Obstacle Detection

Other Products


PX-2

SENSING CHARACTERISTICS (TYPICAL)**PX-21 PX-23ES****Sensing fields**



• All areas effective (Horizontal)





• C. area effective (Horizontal)





• All areas effective (Vertical)

**Correlation between external sensitivity adjustment input voltage and sensing range (PX-23ES only)****Correlation between sensitivity adjuster and sensing range**


• OUT1 (OUT2) area





• Adjacent right (left) OUT1 area

**PX-26****Sensing fields**

• Horizontal [All areas effective (Note)]





• Vertical [All areas effective (Note)]

**Correlation between external sensitivity adjustment input voltage and sensing range**



Note: Area selection is not possible.

Correlation between sensitivity adjuster and sensing range

• OUT1 (OUT2) area




• Adjacent right (left) OUT1 area



SENSING CHARACTERISTICS (TYPICAL)**PX-SB1****Sensing field**

- Horizontal and vertical directions

**PRECAUTIONS FOR PROPER USE**

Refer to General precautions.

All models

- Never use this product as a sensing device for personnel protection.
- In case of using sensing devices for personnel protection, use products which meet laws and standards, such as OSHA, ANSI or IEC etc., for personnel protection applicable in each region or country.

Hazard Indications

In this catalog, **WARNING** and **CAUTION** are indicated depending upon the level of danger. Please observe them strictly for the safe use of this sensor.

WARNING

'WARNING' indicates a potentially hazardous situation that, if not avoided, could result in death or serious injury.

CAUTION

'CAUTION' indicates a hazardous situation that, if not avoided, may result in minor or moderate injury. Further, they also indicate the condition of risk of physical damage to machinery.

WARNING**• Installation of a touch bumper**

You are requested to always install a touch bumper when this product is used on an automatic guided vehicle (AGV).

CAUTION**• Use outside Japan**

This sensor conforms to the EMC Directive. However, it is not certified by a competent body in accordance with other country safety standards. Since each country has its regulations, please follow the local and national regulations of the country where this sensor is used.

CAUTION**• Fail-safe measures**


This sensor is meant for proximity detection and does not possess control functions for safety maintenance. If fail-safe measures are required, consider their incorporation in the total system. Further, do not connect the sensor output directly to a stopping mechanism (brake).

CAUTION**• Periodical maintenance check**


The person in charge must periodically confirm the performance of the product and maintain a record of such checks. In addition, whenever the operating environment of the product is changed due to system modification, etc., performance check must be done.

Mounting


- The tightening torque for the main sensor should be 1.2 N·m or less.



- The tightening torque for **PX-SB1** (auxiliary sensor) should be 0.8 N·m or less.



- Mount the sensor, horizontally, at least 300 mm **11.811 in** above the floor, to avoid reflection from the floor.



FIBER SENSORS

LASER SENSORS

PHOTO-ELECTRIC SENSORS

MICRO PHOTO-ELECTRIC SENSORS

AREA SENSORS

LIGHT CURTAINS

PRESSURE / FLOW SENSORS

INDUCTIVE PROXIMITY SENSORS

PARTICULAR USE SENSORS

SENSOR OPTIONS

SIMPLE WIRE-SAVING UNITS

WIRE-SAVING SYSTEMS

MEASURE-MENT SENSORS

STATIC CONTROL DEVICES

ENDOSCOPE

LASER MARKERS

PLC / TERMINALS

HUMAN MACHINE INTERFACES

ENERGY CONSUMPTION VISUALIZATION COMPONENTS

FA COMPONENTS

MACHINE VISION SYSTEMS

UV CURING SYSTEMS

Selection Guide

Wafer Detection

Liquid Leak Detection

Liquid Level Detection

Water Detection

Color Mark Detection

Hot Melt Glue Detection

Ultrasonic

Small / Sim Object Detection

Obstacle Detection

Other Products

PX-2


PRECAUTIONS FOR PROPER USE

Refer to General precautions.

All models

Automatic interference prevention function

- In case several sensors are used at the same place, take care that the number of sensors from which beams may be simultaneously incident is 25 sensors or less.




Simultaneously incident beam from up to 25 sensors.

Sleep function (Incorporated in all models)

- When the sleep input is made Low, the sensor goes into the sleep state and the operation can be stopped. Power consumption during the sleep state is 0.3W max. (Without auxiliary sensors).

- Notes: 1) Response time of the sleep input is 50ms.
 2) Reactivation from the sleep state to the operation state takes 0.7 sec. approx. Operation during this transient state should be avoided.
 3) When the sleep function is not used, keep the sleep input wire open or insulated and prevent contact with other wires.

Part description



Sign	Item	Description
①	Operation indicator	OUT 2 area (Yellow LED) Lights up when the beam is received in the OUT 2 area.
②		OUT 1 area (Red LED) Lights up when the beam is received in the OUT 1 area.
③	Sensitivity adjuster	OUT 2 area Sensing area sensitivity adjuster.
④		OUT 1 area
⑤		Adjacent right OUT 1 area
⑥		Adjacent left OUT 1 area
⑦	Sensing area selection switch (Note 1)	Left area Selection of main sensor sensing areas. (OUT 1, OUT 2) Left area: Effective (RL), Ineffective (OFF, RL, OFF)
⑧		Right area Right area: Effective (RL), Ineffective (OFF, RL, OFF)
⑨	Output operation mode selection switch	Select the operation mode for OUT 1 and OUT 2 with the operation mode selection switch. D.ON: Light-ON, L.ON: Dark-ON, D.ON: Dark-ON, L.ON: Light-ON
⑩	External control function selection switch (Note 2)	Select whether to perform selection of sensing area with the dipswitch or by external input. INT.: Dipswitches, EXT.: External inputs

Notes: 1) Not incorporated in **PX-26**.
 2) Incorporated in **PX-24ES** and **PX-23ES**.

Others

- Do not use during the initial transient time (0.7 sec.) after the power supply is switched on.
- Take care that an initial rush current (1.5 A approx. at 10 V DC and 5 A approx. at 31 V DC) will flow when the power supply is switched on.

PX-22 PX-21 PX-24 PX-24ES PX-23ES

Selection of sensing area

Setting method	Internal settings INT. EXT.	Area selection input (Note) (PX-24ES and PX-23ES only)		
		Input 1	Input 2	Input 3
All areas ineffective 	—	L	L	L
Center area effective 	—	H	L	L
Center, right and adjacent right OUT 1 areas effective 	—	L	H	L
Center left and adjacent left OUT 1 areas effective 	—	H	H	L
Center and left / right adjacent OUT 1 areas effective 		L	L	H
Center, right and adjacent left / right OUT 1 areas effective 		H	L	H
Center, left and adjacent left / right OUT 1 areas effective 		L	H	H
All areas effective 		H	H	H

L: Low (0 to 1V), H: High (4.5 to 31V, or open)

Note: Response time of area the selection input is 80 ms.

PRECAUTIONS FOR PROPER USE

Refer to General precautions.

PX-24 PX-24ES PX-23ES PX-26**External sensitivity adjustment function**

- The sensitivity can be adjusted, within the range set by the manual sensitivity adjuster, by an analog voltage (0 to +5 V) applied to the external sensitivity adjustment input. The sensitivity varies with the magnitude of the applied voltage.


Notes: 1) The sensitivity of the auxiliary sensor is not changed.
 2) Sensitivity adjustment beyond the range set by the manual sensitivity adjuster is not possible.

Input voltage	0 V $\longleftrightarrow$ +5 V or open
Sensitivity	Minimum $\longleftrightarrow$ Maximum (Maximum sensitivity set by the manual sensitivity adjuster)

3) This wire should be insulated if it is not used.

Extraneous light monitor function(Not incorporated in **PX-22** and **PX-21**)

- If the sensor receives modulated light other than its own (including auxiliary sensor's) light, the extraneous light monitor output turns ON. The operation of the extraneous light monitor output has absolutely no affect on sensing. It is useful for recognizing presence of other sensors near this sensor in case of intersecting AGV paths, etc.



Note: The extraneous light monitor output is not incorporated with a short-circuit protection circuit. Do not connect it directly to a power supply or a capacitive load.

PX-SB1

- This sensor must always be used with the applicable main sensor. This sensor does not work as a standalone unit. (It cannot be used with **PX-22** or **PX-21**.)

Selection of auxiliary area

- Aux area can be selected by aux area ineffective input of the main sensor.


Ineffective input	Auxiliary left OUT 1 area	Auxiliary right OUT 1 area
Sensing area		
Auxiliary left / right OUT 1 area ineffective 	L	L
Auxiliary left OUT 1 area effective 	H	L
Auxiliary right OUT 1 area effective 	L	H
Auxiliary left / right OUT 1 area effective 	H	H

L: Low (0 to 1 V), H: High (4.5 to 31 V or open)

Note: Aux area disable input has nothing to do with the external control function selection switch of the main sensor.

Sensitivity setting

- Sensitivity adjustment of **PX-SB1** is performed with the emitter volume. If sensitivity cannot be set to close range even after adjusting the emitter volume, then an aux sensor might be receiving the light from the main sensor. If that is the case, adjust sensitivity with the emitter volume and the receiver volume. For details, see the instruction manual that comes with the product.

Connection with the main sensor

- Connect the main sensor connector attached cable to the aux sensor connector attached cable.
- The spiral lead wire side of the main sensor connector attached cable is the left aux sensor side.

FIBER SENSORS

LASER SENSORS

PHOTO-ELECTRIC SENSORS

MICRO PHOTO-ELECTRIC SENSORS

AREA SENSORS

LIGHT CURTAINS

PRESSURE / FLOW SENSORS

INDUCTIVE PROXIMITY SENSORS

PARTICULAR USE SENSORS

SENSOR OPTIONS

SIMPLE WIRE-SAVING UNITS

WIRE-SAVING SYSTEMS

MEASURE-MENT SENSORS

STATIC CONTROL DEVICES

ENDOSCOPE

LASER MARKERS

PLC / TERMINALS

HUMAN MACHINE INTERFACES

ENERGY CONSUMPTION VISUALIZATION COMPONENTS

FA COMPONENTS

MACHINE VISION SYSTEMS

UV CURING SYSTEMS

Selection Guide

Wafer Detection

Liquid Leak Detection

Liquid Level Detection

Water Detection

Color Mark Detection

Hot Melt Glue Detection

Ultrasonic

Small / Sim Object Detection

Obstacle Detection

Other Products


PX-2

DIMENSIONS (Unit: mm in)

The CAD data in the dimensions can be downloaded from our website.

PX-2□


Main sensor



Note: **PX-22** and **PX-21** do not have this cable.

PX-SB1

Auxiliary sensor





DIMENSIONS (Unit: mm in)

The CAD data in the dimensions can be downloaded from our website.

MS-PX-2

Main sensor mounting bracket (Accessory for PX-2□)





Material: Cold rolled carbon steel (SPCC)
(Uni-chrome plated)

Four M4 (length 8 mm 0.315 in) screws with washers are attached.

Assembly dimensions

Mounting drawing with PX-24

FIBER
SENSORSLASER
SENSORSPHOTO-
ELECTRIC
SENSORSMICRO
PHOTO-
ELECTRIC
SENSORSAREA
SENSORSLIGHT
CURTAINSPRESSURE /
FLOW
SENSORSINDUCTIVE
PROXIMITY
SENSORSPARTICULAR
USE
SENSORSSENSOR
OPTIONSSIMPLE
WIRE-
SAVING
UNITSWIRE-
SAVING
SYSTEMSMEASURE-
MENT
SENSORSSTATIC
CONTROL
DEVICES

ENDOSCOPE

LASER
MARKERSPLC /
TERMINALSHUMAN
MACHINE
INTERFACESENERGY
CONSUMPTION
VISUALIZATION
COMPONENTSFA
COMPONENTSMACHINE
VISION
SYSTEMSUV
CURING
SYSTEMSSelection
GuideWafer
DetectionLiquid Leak
DetectionLiquid Level
DetectionWater
DetectionColor Mark
DetectionHot Melt Glue
Detection

Ultrasonic



Small / Sim
Object DetectionObstacle
DetectionOther
Products**PX-2**

DIMENSIONS (Unit: mm in)



The CAD data in the dimensions can be downloaded from our website.

MS-NX5-1



Auxiliary sensor mounting bracket (Accessory for PX-SB1)

Material: Cold rolled carbon steel (SPCC)
(Uni-chrome plated)Two M4 (length 25 mm 0.984 in)
screws with washers and two M4 nuts are attached.**Assembly dimensions****MS-NX5-2**

Auxiliary sensor mounting bracket (Optional)

Material: Cold rolled carbon steel (SPCC)
(Uni-chrome plated)Two M4 (length 25 mm 0.984 in) screws with washers and
two M4 nuts are attached.**Assembly dimensions****MS-NX5-3**

Auxiliary sensor mounting bracket (Optional)

Material: Cold rolled carbon steel (SPCC)
(Uni-chrome plated)Two M4 (length 25 mm 0.984 in) screws with washers and
two M4 nuts are attached.**Assembly dimensions**FIBER
SENSORSLASER
SENSORSPHOTO-
ELECTRIC
SENSORSMICRO
PHOTO-
ELECTRIC
SENSORSAREA
SENSORSLIGHT
CURTAINSPRESSURE /
FLOW
SENSORSINDUCTIVE
PROXIMITY
SENSORSPARTICULAR
USE
SENSORSSENSOR
OPTIONSSIMPLE
WIRE-SAVING
UNITSWIRE-SAVING
SYSTEMSMEASURE-
MENT
SENSORSSTATIC
CONTROL
DEVICES

ENDSCOPE

LASER
MARKERSPLC /
TERMINALSHUMAN
MACHINE
INTERFACESENERGY
CONSUMPTION
VISUALIZATION
COMPONENTSFA
COMPONENTSMACHINE
VISION
SYSTEMSUV
CURING
SYSTEMSSelection
GuideWafer
DetectionLiquid Leak
DetectionLiquid Level
DetectionWater
DetectionColor Mark
DetectionHot Melt Glue
Detection

Ultrasonic

Small / Slim
Object DetectionObstacle
DetectionOther
Products

PX-2

MEMO