




Tensioning connector



- Tensioning connector for fast assembly
- The connector can be moved within the slot
- Easily accessible screws
- Three slots are left free for mounting surface elements
- Profile finishing: not required

Technical data (p. 19-8)

P			
30x...	1000 N	35 Nm	15 Nm
45x...L	3500 N	110 Nm	30 Nm
40x..., 45x..., 50x..., 90x...	3500 N	110 Nm	30 Nm
60x...	3500 N	195 Nm	60 Nm

Tensioning connector	Slot	P	ESD		No.
8	8	30x...		10	3 842 538 489
10L	10	45x...L		10	3 842 538 491
10	10	40x..., 45x..., 50x..., 60x..., 90x...		10	3 842 538 490

Material: steel; galvanized