




ENGLISH

Datasheet

RS Pro Electronic Digital Caliper 200mm Metric Only

RS Stock No: 877-1775



Specifications:

Hardened stainless steel frame and measuring jaws

Thumbroll adjustment

Knurled locking screw

Depth rod

Clear LCD Display

Large 11mm digits

Origin setting

Resolution: 0.01mm

Repeatability: 0.01mm

4 Way measurement:

Individual serial numbers

Power: 1 x Silver oxide battery SR44 - 1.55v

Operating temperature: 5 - 40°C

Relative humidity: Maximum 80%


Warranty: 1 year

Order Code	Manufacturers Code	Description
877-1775	49-923-255	Electronic Digital Caliper 200mm

Datasheet

RS Pro Electronic Digital Caliper 200mm

Metric Only



Range	Resolution	Repeatability	External Jaw Length	Internal Jaw Length
200mm	0.01mm	0.01mm	50mm	20mm

Accuracy:

$\pm 0.02\text{mm}$ ($\leq 100\text{mm}$)

$\pm 0.03\text{mm}$ ($\geq 100\text{mm} - 200\text{mm}$)

$\pm 0.04\text{mm}$ ($\geq 200\text{mm} - 300\text{mm}$)




ENGLISH

Datasheet

RS Pro Electronic Digital Caliper 200mm

Metric Only

4 Way Measurement Feature:



Operating Instructions:

When using the Caliper for the first time or after a period of non-use, wipe the beam scale with a dry clean cloth to remove any condensation or oil deposits.

Prior to setting the caliper for measuring, first clean the measuring faces with a soft clean cloth or paper.

Switch Caliper ON

Move Caliper jaws together.

Select required measuring mode Inch / Metric.

Zero display, caliper is now ready for direct measurement.

Caliper can be zeroed at any position within its range, to provide relative measurements.

Caliper provides 4 way measurements, External, Internal, Step and Depth.



ENGLISH

Datasheet

RS Pro Electronic Digital Caliper 200mm Metric Only

Operating Care:

Clean measuring faces with dry soft cloth

Keep away from strong magnetic fields

Prevent ingress of oil / liquids into electronics

Remove battery if instrument is not used for a long period of time

Do not disassemble or drop the instrument

Do not mark instrument by engraving, etching or any other permanent marking method, as this will invalidate the warranty

Fault Finding:

Fault	Cause	Action
Display flashes	Battery voltage below 1.45volts	Replace battery
Display frozen	Circuit overload	Remove battery and replace after 4 minutes
Accuracy below specification but within +/- 0.1mm	Dirt in sensor	Remove slider cover assembly, clean face of sensor with dry clean compressed air (5kg/cm ²)
No display	Poor battery contact	Remove battery and carefully adjust battery contacts, replace battery.
	Dead battery	Replace battery.