

# Accessory

## Safety Rests

**Safety rests for all Weller soldering and desoldering tools, complete with sponge.**  
**See survey "Safety Rests" on page 66**



Order No.	Model	Description
005 15 010 99	AK 1	Safety rest for DS 80 (+ UNC), DSX 80 desoldering iron, LR 21, LR 82 soldering iron, HAP 1 hot air pencil W 61, W 101 and WSP 150 with soldering smoke exhaust



005 15 045 99	AK 10	Safety rest without sponge for HAP 2 (WHA 2000), HAP 3 (WHA 700)
---------------	-------	--



005 15 004 99	KH 4	Safety rest for W 61 soldering iron with straight tip
005 15 006 99	KH 6	Safety rest for W 101 soldering iron with straight tip



005 15 019 99	KH 15	Safety rest for MLR 21 soldering iron
---------------	-------	---------------------------------------



005 22 419 99		Surrogate sponges (5 pcs.)
---------------	--	----------------------------



T005 13 840 99		Brass cleaning wool for WDC (2 pieces)
T005 13 841 99		Brass cleaning wool WDC 2 (2 pieces)



- No-clean flux
- Minimizes tip erosion
- Flux share: 3.5 %
- Doubles soldering tips life
- Fast wetting, even on difficult surfaces
- Optimized flux for less solder splas

### WSW Lead-free solder wire for longer tip lifetime

Soldering wire with integrated flux core

- Superior wetting properties
- Cost reduction due to reduction in tip change frequency
- Not flux soaked - no process pollution
- Reduced spring effect - less solder splashes
- Reduction of service costs for removing of oxidised layers
- Prolonged soldering tip lifetime



Order No.	Model	Description
T005 13 842 99	WSW	Soldering wire ø 0.5 mm; 250 g
T005 13 843 99	WSW	Soldering wire ø 0.8 mm; 250 g
T005 13 845 99	WSW	Soldering wire ø 1.0 mm; 250 g