



ENGLISH

# Datasheet

## Ferric Chloride Stain Remover

RS Stock number 216-2699



### Features

This unique powder may be utilised in a variety of methods for the removal of Ferric Chloride stains from clothing, PCB tanks, work benches and other affected areas.

Concentration required will depend upon the nature of stain requiring removal but typical concentration in solution is between 100g/200ml and 100g/1000ml of water. The powder may also be used direct on badly affected areas.

### Specification

Ferric stain remover is an organic acid and wet powder and solutions have a burning effect on cuts and wounds. Always wear suitable protective gloves and goggles when handling.

All items of clothing that have been treated must be thoroughly rinsed after processing and then machine washed before wearing.

All equipment, machine parts or any other treated items or areas must also be thoroughly rinsed after cleaning.